



How to Update driver on Windows 10 Anniversary For EW-7611ULB

Configuration Steps


1. Plug EW-7611ULB into the computer.
2. Click right mouse on This PC, and select Manage.




3. Click Device Manager, click Network adapter, and click right mouse on Edimax Wi-Fi N150 Bluetooth4.0 USB Adapter, and select Update Driver Software.




4. Click the red-box as below.




5. Click red-box s below.



6. Select USB Composite Device, and click Next.



7. It will update driver automatically. Click Close.



8. You will see it as red-box as below without an **exclamation mark**.

